

User Manual for Laser Marking Machine

Suzhou Friends Laser Technology Co., Ltd.

Integrity Innovation Cooperation Sharing

Version: A1

The final interpretation right belongs to our company

Drafted by	Reviewed by	Approved by
2024/8/8 Jiaqing Fan	2024/8/8 Zhenyu Zhou	2024/8/8 Steven Li

Document update history

Version	Change Content	Issue Date	Created by	Remark
A0	New document	8 th , Aug,2024	Jiajing Fan	
	release			





Catalogue

Security information	1
1 Power on/off sequence	3
2 Mouse usage tips	3
3 Edit text content and parameters	3
4 Edit vector graphics file	9
5 Parameter setting and debugging	13
6 Fixing fixtures and adjusting marking positions	17

Please read this manual carefully before using the equipment.

Security information

A. Safety signs



May cause serious personal injury or even endanger life



may cause general personal injury or damage to products or equipment.

B. Laser Safety Level

According to the European Standard EN 60825-1, Clause 9, the device's internal laser belongs to 4 types of lasers. the product emits laser radiation at wavelengths around 1064 nm or 1080 nm, causing damage to the eyes and skin directly or indirectly exposed to such light intensity. Although the radiation is invisible, the beam can cause irreparable damage to the retina or cornea. Suitable and certified laser protective glasses must be worn during laser operation.





C. Security identification



1.1 Laser identification

1.2 Do not fold the fiber

D. Electrical safety

①grounding the product through the PE line in the power cord, and ensure the grounding is firm and reliable.



Grounding disconnection will cause the product shell to be charged, which may cause personal injury to the operator.

②Ensure AC voltage supply is normal.



Wrong wiring or supply voltage will cause unrecoverable damage to the laser.

1 Power on/off sequence

1.1 Power on operation steps

Step 1: Confirm that the emergency stop switch is in the pop-up state. If it is in the closed state, release the emergency stop switch in the direction indicated by the arrow on the button.

Attention: The emergency stop switch is a forced power-off button used in the event of a temporary malfunction of the equipment. During the normal operation of daily equipment, the emergency stop switch should not be pressed, otherwise it may cause the equipment to suddenly shut down abnormally, affecting the normal service life of equipment components and the loss of related unsaved files.

Step 2: Turn on the main power circuit breaker;

Step 3: Rotate the control key switch clockwise, the power indicator light will turn on, and the main control box will be powered on;

Step 4: Turn on the monitor and Start the industrial computer;

Step 5: Double click the EzCad2 shortcut icon on the desktop as shown in Figure 1-1 to open the EzCad2 marking software.



Figure 1-1

1.2. Shutdown operation steps

Step 1: Exit the marking software.

Step 2: Turn off the industrial computer and monitor.

Part 3: Rotate the control key switch counterclockwise, and the power indicator light will be off. Step 4: Turn off the main power switch.

2 Mouse usage tips

2.1 Push the scroll wheel forward to shrink the interface;

2.2. Pull the scroll wheel backwards to enlarge the interface;

2.3. Hold down the scroll wheel, move the mouse, and the interface will follow the mouse movement;

2.4. When selecting an object, hold down the left mouse button in the upper left corner of the target object, and then drag the mouse to the lower right corner of the target object to select the object (i.e. select the object in the forward direction). The target object needs to be completely enclosed before it can be selected;

2.5. When selecting an object, hold down the left mouse button in the lower right corner of the target object, and then drag the mouse to the upper left corner of the target object to select the object (i.e. select the object in the opposite direction). This method only requires touching the object to select it.

3 Edit text content and parameters

3.1. Draw text

Step 1: Select the "Text" command from the drawing menu or click on the





Step 2: Under the command to draw text, move the mouse to the workspace and click the left button to create a text object, as shown in Figure 3-1;



Figure 3-1 Text Object

Step 3: Select the text object. You can edit the text content that needs to be marked in the text editing box in the left text attribute/property bar. The text editing box is shown in Figure 3-2. After editing the text content, click "Apply", and the text object will be displayed as the modified text content.

Text			×
Роз х (-5. у (-2. Z (0	ition S 034 12. 149 7.3	ize[mm] 314 94	
Array	INPORT	Apply	
Font	TrueTyp	e Font-39	•
Adobe	楷体 Std	l R	•
H	F		
۰Ť	ਸਿ ਾ	⊤ ਾ	Ť
Space		1	
Height	:	10mm	
Text			
TEXT			<u>`</u>
<		>	
T Ens	ble vari:	able Text	

Figure 3-2 Text Attribute/property

3.2. Modify text properties

After selecting the text object, the text properties shown in Figure 3-2 will be displayed in the properties toolbar.

(1)

Refers to the position coordinates and size dimensions of the text within the workspace;

Text	×
Position x -5.034	Size[mm] 12.314
¥ -2.149	7. 394

(2) There is a locker icon, (a), in the text properties. When modifying dimensions, scaling proportionally;



富润泽激光 診 FRIENDS *LASER Suzhou Friends Laser Technology Co., Ltd. Integrity, Innovation, Cooperation, Sharing
③ After clicking on the icon, , it becomes the icon, , indicating unequal scaling when modifying the
size;
④ The reference point 💷 whose position coordinates are within the work area;
(5) To modify any parameter in the attribute bar, you need to click, Apply, "Apply" to modify it to the target object;
6 Fill parameters for text objects by clicking III;
(7) F, Refers to the font parameters of the text object;
8 Font TrueType Font-3 () Adobe 楷体 Std R , The font type of the text object;
(9) Height 10mm, The average height of the font;
(10) Text editing box
Enchle verichle Text
(1) After clicking/selecting

system will display the variable text properties as shown in Figure 3-3. Variable text refers to the dynamic change of text content during the processing according to user-defined rules. For detailed introduction, please refer to page 53 of the software user manual.

✓ Enable ✓ TT	variabi Text
	Add
	Delete
	Prev
	Next
	Modify
Array	Advance

Figure 3-3 Variable Text Attributes

3.3. Modify the font type of the text

EzCad2 supports five font types: TrueType font, single line font, dot matrix font, barcode font, and SHX font, as shown in Figure 3-4.





字体	TrueType字体-226 💌
Arial	TrueType字体-226 单线字体-8 点阵字体-1 条形码字体-31 SNX字体-0

Figure 3-4 Font Types

Figure 3-5 TrueType Font List

Note: The number after the font type refers to the number of fonts in the system. If there are no specified fonts in the font list, you can download the font library online and install it in the "My Computer/C Drive/Windows/Fonts" font library.

After selecting the font type, the font list will correspondingly list all fonts of the current type, as shown in the TrueType font list in Figure 3-5. You can select the required font from the font list, and click 'Apply' to change the text content to the font type we have chosen.

3.4 Modify font parameters

Select the edited text, click on the text properties *I*, and the system will pop up a font parameter dialog box as shown in Figure 3-6.



Font	×
E E Bold [Italio	Orientation • Horizontal • Vertical
Char Width 50 % Char	, reitical
Char Angle 0 deg (-89,89)	
Char space 0 mm	
Line space 0 mm	
Empty char width 0 %	
Circle Text Circle Diameter 10 Base angle 90 Angle range limit 90 (1-360)	
Apply OK Cancel	L



- ① E, The current text is arranged in a left aligned manner;
- Align the current text in a centered manner;
- ③ Image: Bight aligned refers to the arrangement of the current text;
- (4) The characters drawn are in bold font after selecting \Box Bold;
- 5 The drawn text is italicized after selecting [Italian];

Orientation Horizontal Vertical

- 6 The direction of font arrangement is horizontal or vertical by selecting
- All characters have the same width;
- 8 Char Width 50 % Char. The average width of a characters;
- (9) Char Angle 0 deg (-89, 89) The inclination angle of the characters;



(10)

The spacing between characters.

After modifying the font parameters, click "OK" or "Apply" to apply them to the edited text.

3.5 Draw arc text

Char space

3.5.1 Click on "Circle" in the drawing menu, or click on the icon —, move the mouse to the workspace, left click and drag the mouse, then release the left mouse button and right-click to draw a circle in the workspace. The diameter of the required circle can be modified in the left object property bar, as shown in Figure 3-7.

Position Size[mm] X -35.317 25.946 Y 8.654 25.946 Z 0 Image: Constraint of the second se
Array INFORT Apply
Diameter 25.946
Start Angle 90 deg
\$

Figure 3-7 Object Attribute Bar

3.5.2 Click on "Text" in the drawing menu, or click on the icon **1** and left click on the arc of the drawn circle. The text will be arranged as shown in Figure 3-8.



Figure 3-8 Text Arrangement

3.5.3 Select the text object and click in the left object property bar. The system will pop up a dialog box as shown in Figure 3-9.



PathText	×
Transform	
Base Base	
Base length O Offset length	
Base angle 90	
Angle range limit 90 (1-360) Circle Diameter	
37. 044	1
Apply OK Cancel	

Figure 3-9 Curve Text Parameter Dialogue Box

For detailed instructions on curve text parameters, please refer to pages 43-46 of the EZcad software user manual.

4、 Edit vector graphics file

1. Confirm the format of the drawing file

The commonly used vector file format for marking software is DXF/AI:

DXF: If the drawing file is created using Auto CAD, select the "Auto CAD2000/LT2000DXF" format when saving the file, and then import the saved drawing file into the marking software for use;

AI: If the image file is in another format, it can be converted to AI format and exported using CoreIDRAW software, and then the exported AI image file can be imported into the marking software for use.

2. Use CoreIDRAW software to convert image file formats

Step 1: Double click the desktop CoreIDRAW software shortcut icon, as shown in Figure 4-1, to open the CoreIDRAW software;



Figure 4-1 CoreIDRAW software

Step 2: Click on "File - Import", and a dialog box as shown in Figure 4-2 will pop up. Select the file that needs to be converted, click "Import", and then click "OK" in sequence until the file import software interface appears;











Figure 4-3 Export File Dialogue Box

Step 4: Click "Export", and a dialog box as shown in Figure 4-4 will pop up. Modify the options according to the content shown in the figure, and then click "OK" to complete the file format conversion. At this point, enter the marking software to import the converted file.



Suzhou Friends Laser Technology Co., Ltd. Integrity, Innovation, Cooperation, Sharing

Compatibility	Adobe Illustrator 导出	Adobe Illustrator Export
Target file □PCP	兼容性(C): Adobe Illustrator 8.0 目标文件 PC(P) Macintosh(M)	Export the file as Curve(U) or Text(T)
□Macintosh	 导出文本为 ● 曲线(U) ● 文本(T) ■ 转换专色为三色(S) ■ 使用当前预置文件校正颜色(R) 	 Convert the special color into 3-color; Use current pre-set file to calibrate color; Simulate the profile effect Simulate complex filled shapes
Confirm	 □ 模拟轮廓效果(0) □ 模拟复杂的已填充曲线(F) ☑ 包含已放置的图像(I) ☑ 包括预览图像(N) 	□ Including the placed image □ Including pre-view image
Cancel	<u>确定</u> 取消 帮助(H)	Help

Figure 4-4 AI Export Dialogue Box

3. Edit vector files

Step 1: Select the "Vector File" command or click the icon, 22, in the drawing menu. The system will pop up a dialog box as shown in Figure 4-5. Select the vector file you want to import, click "Open", and import the vector file;

Open	Document path	
	🔝 धाम	×
	查找范围(I): ▲面下载 · • • • • • • • • • • • • • • • • • •	
	Ezcad2.14.1(20 Ezcad2.14.8(20 韩国机器参数 新建文件共	E ~
	ABC Bearing Limited 2.dxf	Open
	文件名(N): test tasma.plt	打开(0)
	文件类型(T): All vector Files(*.ai;*.plt;*.dxf;*.dst;*.svg;*.nc;*	用交流的
	Show preview Put to center def file upit is inch	
File Type		Cancel

Figure 4-5 Vector File Input Dialogue Box

Note: Often times, after importing a graphic file, it cannot be seen in the workspace. We can observe the object



list and vector file attribute bar on the left, as shown in Figure 4-6. From the object list, we can see the vector file that has been imported,

but from the file's position coordinates, it can be seen that the graphic file is outside the workspace. At this point, click the icon to center the graphic file and place it at the origin. The vector file position coordinates will change to (X=0, Y=0), and we can see the graphic file in the workspace.



Figure 4-6 Object List and Attribute Bar

Step 2: Select the imported vector image file, click on the icon , , continuously to dissolve the group until

the icon turns gray color, . At this point, we can see in the object list that the vector file has become many curves;

Step 3: Select the unwanted curves (there may be many curves that are needed and unnecessary that are intertwined, and we can use the method of selecting objects in the opposite direction mentioned above to

select the unwanted curves), and click the icon, is , to delete these curves;

Step 4: Select the remaining curves, click the group icon, ..., and group the curves we need to mark together. (It is also possible to rent each marked object individually in a group, which makes it more convenient for each object to adjust its position separately.)

Now that the image file is edited, you can adjust the parameters according to the desired effect.

5 Parameter setting and debugging

5.1. Set filling parameters

If the content we need to mark is an entity, we can select the object that needs to be filled and click the icon,

In to fill it (if no object is selected, this icon will be gray, and there will be no response when clicked).
At this time, the fill parameter dialog box as shown in Figure 5-1 will pop up.



🔽 Mark Conto	ur [4	ОК
	C 2 (3	Concel
🔽 Enable		Туре	Cancer
All calc	3	\leq	Delete Hatch
Follow ed	ge on _		
Angle	Pen	No.	- Hatch one by one
0 deg	0	•	i nation one by one
Count	1	Ī	
Line Distance	0.01		
🔽 Average dis	stribute	e line	
Edge Offset	0	m	
Start Offset	0	mm	
End Offset	Ō		
Linereduction	0	mm	
NumLoops	0		
Loop distance	0.5	mm	
Auto rora	te angl	e	
10	deg		

Figure 5-1 Filling parameter setting column

The definition of each item in the settings column can be found in the introduction on pages 15-20 of the software user manual. Here, I will talk about the range of **Line Distance** settings for some commonly used processes:

◆ The range of line distance for stainless steel whitening and aluminum whitening is

0.03mm-0.05mm;

◆ The range of line distance for stainless steel blackening and aluminum blackening is

0.005mm-0.02mm;

• The range of black line distance for stainless steel without tactile sensation is 0.005mm-

0.01mm;

The line distance range for marking lines on plastic materials is 0.04mm-0.08mm.

2. Find the focus

Laser is focused into a small spot through a lens, and then controlled by a galvanometer to scan the edited text or graphics on the processing surface. Therefore, before debugging, the focus should be adjusted to the processing surface.



Suzhou Friends Laser Technology Co., Ltd. Integrity, Innovation, Cooperation, Sharing

First, draw a random pattern in the work area. Then, in the processing control bar shown in Figure 5-2, click on "Red Light" (or press F1 on the keyboard). The position indicated by the red light is the marking position. Place the metal sheet on the surface of the workpiece at the red light position, then check for continuous processing. Click "Marking" (or press F2 on the keyboard), adjust the lifting platform to the brightest and loudest height of the marking, and then click "Stop" (or press ESC on the keyboard) to stop marking. At this point, the focus is on the surface of the workpiece. (After adjusting the focus, cancel to prevent continuous light output during subsequent debugging)



- Figure 5-2 Processing Control Bar
- 5.3. Parameter settings in the marking parameter column

The marked parameter column is shown in Figure 5-3. We need to debug the speed, power, and frequency. The delay parameters are already set at the factory and do not need to be debugged during use.

5.3.1 Referring to the pen number, different colors represent different strokes, and different pen numbers can set different parameters. Generally, when we have the same marking effect, we can use one pen number;

5.3.2Before checked setting the parameters, usually to "use default parameters", it is

🔽 Use default param . If you need to debug the parameters yourself, you need to uncheck the check

to set the following parameters;

- 5.3.3
- Current pen

0

Refers to the current pen number, black represents "0", and the

corresponding relationship can be seen in the "pen number color" corresponding list above;

Loop Count 5.3.4 Refers to the number of times it needs to be processed, usually 1, requiring multiple unmarked times and can be debugged;

Marking parame			×
Pen No.	C	0n.	
米 O Default		On	
⊁ 1 Default		On	
🗚 2 Default		On	
⊁ 3 Default		On	
🗚 4 Default		On	
⊁ 5 Default		On	
¥6 Default		On	¥
< III.	_) Þ	
🔽 Use defau	lt par	am	
Current pen	0		
Loop Count	1		- <u> </u>
Speed (MM/Sec	ond 50	10	

Power%	50	
Frequency(KHz)	20	
Laser On TC(us)	-150	
Laser Off TC(us	100	-
End TC (us)	200	- <u>-</u>
Polygon TC(us)	50	





Figure 5-3 Marking Properties Table

5.3.5 Speed (MM/Second 500 = Refers to the speed of laser movement, with an adjustable range of 1mm/s-7000mm/s;

- The speed range for blackening stainless steel and aluminum materials, and blackening stainless steel without tactile sensation, is 100mm/s-300mm/s;
- The speed range for whitening stainless steel and aluminum materials, as well as plastic materials, is 1000mm/s-2000mm/s;

5.3.6 **Power%** 50 E Refers to the magnitude of laser energy, with an adjustable range of 0-100%;

- The power setting range for blackening stainless steel and aluminum is 80% -100%, and the higher the power, the darker the marking effect;
- The power setting range for stainless steel without tactile black is 30% -50%;
- The power setting range for stainless steel and aluminum whitening is 50% -80%;
- The power setting range for plastic materials is 1% -80%. Plastic materials are more complex, so the power application range is also wider. Generally, light colored plastics use more power, while dark colored plastics use less power.

5.3.7 **Frequency (KHz)** 20 The speed at which the laser emits laser light, with an adjustable range of 1-400KHz;

- The frequency range for blackening stainless steel and aluminum is 30-40KHz;
- The frequency setting range for stainless steel without tactile black is 80-120KHz;

- The power setting range for stainless steel and aluminum whitening is 40-60KHz;
- The frequency setting range for plastic materials is 10-30KHz.

Laser On TC(us)	-150	-
Laser Off TC(us	100	-
End TC (us)	200	-
Polygon TC(us)	50	

5.3.8

The delay parameters are usually adjusted at the factory and may not be adjusted during use.

In summary, the main parameters to be debugged during the debugging process are speed, power, frequency, and fill line spacing. Speed and line spacing are the two parameters that mainly affect efficiency. At the beginning of debugging, we can set these two parameters according to the material, desired effect, and efficiency requirements, and then debug the power and frequency to achieve the desired effect.

6、 Fixing fixtures and adjusting marking positions

6.1. Fixed fixtures

Step 1: Before fixing the fixture, select all the marked content, click on the icon, \square , to center it, so that the marked content is in the middle of the work area, then click on the "red light" to display the area where the marked content is located. Place the product on the fixture, place the fixture in a suitable position, and insert the screw lock a few cycles, but do not lock it;

Step 2: Gently swing the fixture to ensure that its horizontal or vertical direction is parallel to the horizontal or vertical direction of the red light (this can ensure that the pattern is aligned with the product without any deviation angle during marking), and then fix the fixture. During the fixing process, pay attention to whether the fixture deviates relative to the red light until it is locked.

6.2. Adjust the marking position

There are three main methods to adjust the marking position:

Method 1: Drag with the mouse

After selecting the object to be adjusted, move the mouse to the middle of the object. When the cross arrow appears, click the left mouse button and drag the mouse to adjust the object to any position. During this process, use red light to adjust and roughly adjust the target object to the target position.

Method 2: Use the up/down/left/right arrow keys on the keyboard to adjust

After selecting the adjusting object, press "Up, Down, Left, Right" on the keyboard to move the object in these four directions. The jumping distance of one click can be set in the system parameters;

Select "System Parameters" from the file menu or click on the icon, System Parameters". A dialog box as shown in Figure 6-1 will pop up. Then select "Move and Rotate", and the "Nudge Distance/Fine Adjustment Distance" on the right is the distance that the keyboard object moves each time it is pressed. We can set the size of the "Nudge Distance/Fine Adjustment Distance" as needed, and click "OK" to exit.



General Color WorkSpace AutoSave <u>Move rotate</u> Plug manager User manager	- Keyboar Nudge 1 Big Nu Rotate	d Distance 1.00 dge scale 10.0 15.0	0 mm 0 [deg]
language	To Orig	in6	5
	8	0	4
	1	2	3
	Input	point NO. 0 X 0.0 Y 0.0	00

Figure 6-1 System Parameters

Method 3: Use "Modify Transform" to make precise adjustments

After selecting the target object, select "Transform" in the modification menu. A dialog box as shown in Figure 6-2 will pop up. Then, follow the settings shown in Figure 6-3 to make the XY position 0. At this time, we can enter the exact size we need to adjust in the XY position (right X is a positive value, left X is a negative value, up Y is a positive value, down Y is a negative value). After setting it up, click "Apply", and the target object will move to the position you adjusted.

Transform X
⊕⊙⊴≞⊉
Position
X -1 mm
γ -1 <u>*</u> mm
□ Relatively position
Apply to copy object
Apply

Figure 6-2 Transformation Parameters

↔⊙⊴⊟⊉
Angle
Center X 0 mm
ұ 0 <u>т</u> mm
Relatively center
Apply to copy object
Apply

Figure 6-3 Transformation Parameters after Setting